

Notice



- ☐ CORRECTION ☒ PRODUCTION CHANGE
☐ SERVICE FLASH ☐ ADD INFORMATION

FILE NO.

Please add this notice to the Service Manual listed below.

REVISION 0

Category: **COLOR TELEVISION**

Date: **JULY / 12 / 2011**

Model: **DP46841**

Effective from : Chassis No. **P46841-01**

Destination: **U.S.A. / CANADA**

REF : **No. SM780189-01**

NOTE: Match the Chassis No. on the unit's back cover with the Chassis No. in the Service Manual. **If the Service Manual Chassis No. does not match the unit's**, additional Service Literature is required. This chassis is similar to Chassis No. P46841-00. Only the **difference** Service Information is given in this manual. For detailed Service Information, refer to the **Original** Service Manual and **Notices** for Chassis No. P46841-00 used in Model DP46841 (SM7800189).

SERVICING SHOULD BE PERFORMED BY ONLY TRAINED AND QUALIFIED SERVICE PERSONNEL.

1. IN THE SERVICE ADJUSTMENTS

PAGE 4 ON-SCREEN SERVICE MENU

Item No. **088 OP2 Data** should be changed from **16h** to **17h** in the table and in Note 2.

2. IN THE CHASSIS ELECTRICAL PARTS LIST MISCELLANEOUS

The reason for change.

- | | | |
|------------------------|---------------------------|-------------------------------|
| A : Misprint | B : Quality Reliability | C : Standardization |
| D : Design | E : Add as a possible sub | F : Schematic location change |
| G : Purchasing Request | | |

Page & Section	Schematic Location		Part No.	Description	Q'ty	Interchangeability	Reason
Page 16, Chassis Electrical Parts List	A400	Old	1AA0B10N290B0	ASSY,PWB,POWER Z5VG	1	NO	D
		New	1AA0B10N290C0	ASSY,PWB,POWER Z5WH	1	NO	
	EL901	Old	1AV4T40C27300	LCD(T460HW08 V0)	1	NO	D
		New	1AV4T40C20100	LCD(T460HW03 VF,S11)	1	NO	
	▲WK5LV -PN	Old	1AA4W30B66600	LVDS CABLE,40P-51P	1	NO	D
		New	1AA4W30B67400	LVDS CABLE,40P-51P	1	NO	

For detailed panel (EL901) service differences refer to the following.

P46841-00 (OLD)

Part Number

▲ 819.46T07.002

▲ 855.46T09.C02

Description

INVERTER 40C27300.T460HW08_V0

T-CON/PN 40C27300.T460HW08_V0

P46841-01 (NEW)

Part Number

▲ 86632L-0612A-

▲ 86871L-2144C-

Description

INVERTER LC470WUNS-CA1 40C27400.LC470WUNS-C

T-CON/PN 4T40C20100.LC470WUD-

For parts or service contact:

Sanyo Manufacturing Corporation
P.O. Box 2000
3333 Sanyo Road
Forrest City, Arkansas 72335-2000